

C12

WELL COMPLETION REPORT
3/71

CROTON FALLS

PUTNAM COUNTY DEPARTMENT OF HEALTH

Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P 9/16

41 21 22 73 44 23

OWNER	NAME Robert M. Field, Inc. (No. & Street)		ADDRESS 33 Dogwood Hills Road, Newburgh, NY 12550 (Town) (Lot Number)	
LOCATION OF WELL	Archer Road		Mahopac	
PROPOSED USE OF WELL	<input checked="" type="checkbox"/> DOMESTIC <input type="checkbox"/> BUSINESS ESTABLISHMENT <input type="checkbox"/> FARM <input type="checkbox"/> TEST WELL <input type="checkbox"/> PUBLIC SUPPLY <input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> AIR CONDITIONING <input type="checkbox"/> OTHER (Specify)			
DRILLING EQUIPMENT	<input type="checkbox"/> ROTARY <input checked="" type="checkbox"/> COMPRESSED AIR PERCUSSION <input type="checkbox"/> CABLE PERCUSSION <input type="checkbox"/> OTHER (Specify)			
CASING DETAILS	LENGTH (feet) 20	DIAMETER (inches) 6	WEIGHT PER FOOT 17 lbs.	<input checked="" type="checkbox"/> THREADED <input type="checkbox"/> WELDED DRIVE SHOE <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO WAS CASING DEPUTED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
YIELD TEST	<input type="checkbox"/> BAILED <input type="checkbox"/> PUMPED <input checked="" type="checkbox"/> COMPRESSED AIR		HOURS 1 hr.	G.P.M. 2 YIELD (G.P.M.) 2
WATER LEVEL	MEASURE FROM LAND SURFACE - STATIC (Specify feet) 20 ft.		DURING YIELD TEST (feet) 320 ft.	
SCREEN DETAILS	MAKE			LENGTH OPEN TO AQUIFER (feet)
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED	Diameter of well including gravel pack (inches): GRAVEL SIZE (inches) FROM (feet) TO (feet)

DEPTH FROM LAND SURFACE FEET to FEET		FORMATION DESCRIPTION	Sketch exact location of well with distances, to at least two permanent landmarks.
0	10	Overburden and boulders	
10	300	Gray Granite	

If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE WELL COMPLETED 4/17/85	DATE OF REPORT 5/30/85	WELL DRILLER (Signature) Patricia E. Freligh, Vice President J. T. Eckerson, Inc., Route 9W, Milton, New York 12547
--------------------------------	---------------------------	---